## Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: CHAMPLAIN 1-36H

Field Name: ELKHORN RANCH Well File #: 21523

Date Incident:5/3/2015Time Incident:15:00Facility ID Number:County:BILLINGSTwp:143Rng:101Sec:36Qtr:

**Location Description:** 

Submitted By: Timothy Ilse Received By:

Contact Person: Shane Teigen

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	1	Barrels	1	Barrels	1	barrels	
Brine	4	Barrels	4	Barrels	3	barrels	ı

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 5/12/2015 Clean Up Concluded: 5/3/2015

Risk Evaluation:

None

Areal Extent:

30 ft. by 30 ft. area

## Potential Environmental Impacts:

Well site soil

## Action Taken or Planned:

Contaminated material will be removed and replaced with clean fill.

Wastes Disposal Location: Chimney Butte Disposal

Agencies Involved:

## **Updates**

Date: 5/4/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.